Priority #	County	City	Need	Route	Location	Include bridge(s)?	Description	What problem are you trying to solve?	Status	Notes
1	Greene, Christian, Lawrence, Barry	Billings/ Marionville/ Aurora/ Monett	Capacity and Safety Improvements		Route 60 from Republic (OTO Boundary) to Monett and Route 37 from Monett to Gateway, AR.	A0872 - Fair (6) NP A0871 - Good (7) NP A0870 - Fair (6) NP	Route 60: 4-lane expressway, Republic to Monett and Route 37: 4-lane expressway and/or passing lanes from Monett to Gateway, AR.	Increase capacity in order to accommodate additional freight traffic and assist in economic development in Barry County. A study has already been completed. Safety improvements on narrow and dangerous portions in southern part of the county. Reduce congestion on 60, improve overall safety; increase economic development. This is a freight route for Monett's industry of EFCO/Pella Windows, Tyson Foods, etc. EFCO, a major employer in Monett has said they are about 100 employees behind but can't find employees, in part due to	MoDOT added funds to Rte. 37 resurfacing project 7P3120 in FY 19 for turn lanes and potential passing lanes. MoDOT added project 7P0881, Intersection improvement at Route 60 and Route 37 in FY18. Cost share with Monett. (Not resurfaced in 18-22 STIP) Some environmental work has already been completed 2020- Route 37 pavement resurfacing from Monett to Arkansas with passing lane at Washburn and various intersection improvements	MoDOT and BNSF received a grant for improvements to at-grade crossings on 60.  Mostly around Marionville
2	Lawrence	Mt. Vernon	Capacity and Safety Improvements	on I-44	I-44 and Rt. 39 interchange (Exit 46)		Interchange improvements. Need to extend ramps. Eastbound traffic on ramp to I-44 at exit 46.	Westbound and eastbound (especially westbound is deficient) ramps need improvements. High traffic congestion is anticipated due to TA Traffic Stop. Truck stop is newly opened. Without the ramp extension, traffic will back up on I-44. The traffic isn't high s expected. Trucks are taring the guard rail making turn from the new TA. Needs some widening. The eastbound entrance ramp needs to be lengthened for safety reasons. The ramp is short and it is difficult to see incoming traffic. This is eastbound from the bridge to get into I-44.		
2			Intersection	on Bus. 60	20 (51) 21 (1221)		Upgrade intersection to better accommodate truck traffic; improved	Trucks have to take this very wide and causes safety concerns.		
	Lawrence	Aurora  Mount Vernon	Improvements  New Road  Construction	extends Daniel Drive	at Rte. 39 (Elliot Street) from 1137 to Rte. H		turning radius.  Extension of Outer Road to Hwy H	Pedestrian crossing button needed.  This will alleviate traffic on I-44. It will increase connectivity for the county law enforcement facility and fire station vehicles. This will help decrease emergency response time.		
5	Lawrence	Marionville	Safety Improvements	on Rte. 14	in front of High School		School traffic creates congestion and safety concerns; need a turn lane.  Upgrade intersection to better	There is a new housing subdivision opposite of the school.		
6	Lawrence	Aurora	Intersection Improvement	on Olive St.	at Rte. 39 (Elliot Street)		accommodate truck traffic; freight route			
7	Lawrence	Monett	Capacity/Intersection Improvements Safety	on Rte. H	from Cleveland to 2230		Allow for bigger turning radius. Turn Lane; freight route	Biggest problem: H and Cleveland, especially turning truck/trailer traffic is very bad congestion and safety concerns during school hours. 174 is traveled by tractor trailers and school traffic. Has a high number of pedestrians and	Traffic study (TEAP) completed.	
	Lawrence Lawrence		Improvements Bypass	on Rte. 174 between Rte. 37 and Rte. H	in front of High School		Add a turn lane	vehicles.		
	Lawrence	Aurora	Intersection Improvements	on Rte. 60	at Carnation		Dangerous intersection. Cars turning north where passing lane ends.			
11	Lawrence	Aurora	Bridge/culvert replacement		Lincoln St		Bridge/culvert needs replaced and improved drainage	Near Robinson Elementary School		

							High amount of traffic has caused serious safety concerns. The traffic	
			Safety and Complete			Would like to see complete	count increased from 2014 to 2015 and this area saw 27 crashes in	
	Barry and		Street	on Rte. 37		improvements including a center turn	2015. Including: including 1 fatality, 2 disabling injuries and 4 minor	
12	Lawrence	Monett	Improvements	(Central St.)	from 60 north to city limits	lane.	injuries.	
			Safety				Areas in and around schools, 45 mph speed zone, no place for	
13	Lawrence	Miller	Improvements	on Rte. 39	between 1st and 2nd St	flashing school-crossing sign	pedestrians to safely walk or cross	
							Areas in and around schools, 45 mph speed zone, no place for	
14	Lawrence	Miler	Safety Improvements	on Rte. 39	at 6th St	flashing school-crossing sign	pedestrians to safely walk or cross	
						Difficult to know where to go, shared		
			Safety			lane doesn't have clear markings when	Merge lane is confusing and makes it difficult for people to know how	
15	Lawrence		Improvements	1-44	At Halltown Exit	merging on to go towards Springfield	to use interchange.	
			Capacity			Six-laneing of interstate through		
16	Lawrence		Improvements	1-44	Through County	county	continued increase in traffic and congestion	
			Economic			Upgrade Route H, make		
			Development,			safety/capacity improvements for		
			Capacity				Several large trucks taking a route probably not intended for the traffic;	
17	Lawrence	Through Count	Improvements	Route H	From Monett to I-44	products	heavy freight route.	
						1/4 mile of MoDOT maintained		
			Outer Road		Off N Hwy, South of I-44,	roadway adjacent to County road that		
181	Lawrence		Maintenance	Outer Rd	next to YMCA	needs maintenance		
19	Lawrence	Mount Vernon	Safety & Congestion/Traffic Management	Hwy 39	Mt. Vernon Blvd. & Shafer St.	Intersection needed on Mt. Vernon Blvd.	Intersection is needed to provide safety and reduce potential accident. There are drivers entering and exiting on the Business Loop (Mt. Vernon Blvd). Traffic count provided by MODOT in 2016 12,800 vehicles in 12 hour period. A signalized intersection would reduce the potential for semi/car accidents and relieve congestion. Getting in and out of truck stop is difficult.	
			Intersection			Lights/ mini-roundabout, dangerous		
20	Lawrence	Aurora	Improvement	Bus. 60	at Carnation	intersection		
21	Lawrence	Verona	Safety	Hwy P	Lawrence County Road 2200 and Hwy P	intersection on a curve.	Over the years, safety concerns at this intersection has escalated due to several factors: increasing volume of heavy trucks, both tractor trailers and trash trucks serving numerous commercial industries in Verona, additional os a large Amish community on Hwy P, poor intersectio design of Farm Road 2200 at Hwp P, which has resulted in numerous accidents and near misses. Signageneeds o be added in a better location.	MoDOT redid signing and cut the bush on the intersection.
		1				Bike/Ped		<u></u>
							Need for crosswalk to Dollar General. Rt 39 has high traffic. There is	
					from 6th to Rte. DD	Sidewalk Improvements near school;	safety concern for students. A lot of the students walk from the school	
1	Lawrence	Miller	Bike/Ped	on Rte. 39	(Adamson Street)	·	to Casey's.	
2	Lawrence	Marionville	Bike/Ped	on Rte. 14	from Lincoln to School	Sidewalk Improvements near school		

		1			1		
				Elliott Street (MO-Rt 39) that runs North and South	Sidewalk improvements along Elliott Street to provide access to bike/ped. Need to address stormwater ditches	Increasingly there is pedestrian and bike traffic along Elliott Street for people that are walking to work in the restaurants and retail businesses along Elliott Street, patrons of these businesses and kids that are walking to the High School that do not have automobiles. There is no sidewalks on either side of the road, and large stormwater ditches on either side of the road make it so pedestrians have to walk along the side of the road right next to traffic. MO 39 goes through the City of Aurora (North to South) and is also a major thoroughfare in our community. A large portion of this route/street does not have sidewalks on it. Additionally, from approximately Hadley Street, South to the U.S. 69 MO 39 intersection, there are large ditches on either side of the roadway that are 4 to 7 feet deep with steep sides. This makes pedestrian foot traffic or Bike travel exceedingly dangerous. Anyone daring to traverse this mile of road is, literally, only a foot or two from passing traffic. This section of road also has 7 bridges that cross a major stormwater ditch on the west side of MO 39. This road goes out	
				from Business US 60 to US	that are in the MoDOT ROW and the	to Walmart, crosses U.S. 60, and there was a pedestrian fatality at that	
3 Lawrence	Aurora	Bike/Ped	on Rte. 39	60 through Aurora	installation of Sidewalks.	intersection last year.	City interested in cost share.
4 Lawrence	Aurora	Bike/Ped	Phase III,	South Street from White Park to Lincoln Street.	Trail extension		
5 Lawrence	Marionville	Bike/Ped	on Lawrence and Fiske	from School to Football Field	Sidewalk improvements near school		
3 Lawrence	Iviarionvine	bike/reu	on	Field	Sidewalk improvements hear school		
6 Lawrence	Marionville	Bike/Ped	College/Washingt	from School to Library	Sidewalk improvements near school		
7 Lawrence Jasper/ Lawrence/	Marionville	Bike/Ped	Washington, Jefferson, and Benton St	from School to Square to Park from Central Ave in Carthage to Route Z in	Sidewalk improvements near school  Pave shoulders for bicycle		There are bike rides from SGF to Joplin on
8 Greene		Bike/Ped	on Rte. 96/66	Halltown	accommodations		this route.
9 Lawrence	Aurora	Bike/Ped	on Carnation St	from College St to Hadley	Sidewalk Improvements near school		
					Provide access to ped/bike to move		City responsible for lighting. MoDOT
10 Lawrence	Mount Vernor	Bike/Ped	I-44 Business Loop	Mt. Vernon Blvd.	along Business Loop/Mt. Vernon Blvd.	Lighting is needed for the bus loop.	doesn't assist with corridor lighting.
					Rail		g.
					Need upgrading of dangerous rail		
Lawrence	Marionville	Rail	Numerous	Numerous rail crossings	crossings		
Lawrence	Verona	Rail	W Main St at Railroad Crossing		blocks the intersection for long periods at a time, at times up to 2 hours.	The block caused by the train prevents emergency personnel from crossing the tracks. The only way around the tracks requires travel of 5 miles around the section. This has become an extreme hazard. Further, as this intersection is near S. 3rd Street/St Highway P, we have, at times, had commercial traffic backed up along the highway blocking traffic, backing up on the highway, travelling in the wrong lanes, etc.	
					Transit Expand OATS service frequency and	Monett cause notential consider reduction due to funding outs	
Lawronco		Transit			Scope of Services	Monett saw a potential service reduction due to funding cuts, would like to maintain daily service.	
Lawrence		Transit			Start up/Capital for regional bus	ince to maintain ually service.	
					service between Springfield and		
Lawrence		Transit			surrounding communities		
					Operating Costs from Springfield		
Lawrence		Transit			regional bus service.		
1	•	1			-		

	Aviation										
1							Hanger, Apron and Taxiway expansion-				
1	Lawrence	Mt. Vernon	Aviation		Mt. Vernon Airport		Mt. Vernon Airport Layout Plan				
	Lawrence	Aurora	Aviation		Aurora Airport		Hanger, Apron and Taxiway expansion				